

	Number 08V01 Vendor FSA Notice	2008 F-650 and F-750 Trucks With Allison Transmission - Park Pawl Actuator Assembly Inspection and Repair
Date: May 1, 2008		

INFORMATION ONLY

This Is a Vendor Field Service Action Notice

Model Year	Model	Assembly Plant	Affected Vehicles
2008	F-650 and F-750 trucks equipped with Allison transmissions	ESCOBEDO (MEXICO)	Certain vehicles built from November 16, 2007 through December 11, 2007

Issue

On the affected trucks, Allison Transmission Corporation has determined that a very small number of transmissions may have been produced with a non-conforming park pawl actuator assembly. The non-conforming assembly may cause higher effort in moving the shift selector out of park.

Action

1. Allison Transmission Corporation warrants the transmission park pawl actuator assembly and is conducting a Product Satisfaction Field Action to inspect and, if necessary, repair the park pawl actuator assembly in the affected trucks.
2. Allison Transmission Corporation has contacted all Allison distributors and authorized service centers (including authorized Ford dealers). Allison is providing these facilities with parts, technical instructions, and claiming instructions for the inspection and repair of the park pawl actuator assembly.
3. This notification is for your information only. Allison Transmission Corporation is conducting the Product Satisfaction Field Action and Ford Motor Company has no administrative responsibilities for this action.
4. DO NOT SUBMIT WARRANTY CLAIMS TO FORD MOTOR COMPANY.
5. Allison Transmission Corporation has also sent all affected owners a letter asking them to have the transmission parking pawl actuator assembly inspected and if necessary, repaired at an authorized service center.

NOTE: OASIS is activated to help dealers identify which vehicles may be eligible under this program. Because this is a program being conducted by Allison Transmission Corporation, the Open/Closed status in OASIS will not be updated as vehicles are repaired under the program. As a result, dealers must verify vehicle eligibility with Allison Transmission Company (800-252-5283) prior to performing repairs. Claims are to be submitted directly to Allison Transmission Company.

Questions?	Allison Transmission Call Center:800-252-5283
-------------------	---